

<b>Client: Sample</b>				
<b>Site: Birmingham</b>				
<b>Location: OFFICE</b>				
Asset ID: 3452664	Description: AMPLIFIER	User: A. BARNES	Test Instrument: Seaward PrimeTest 350 04B-0195	
Comments: DAMAGED CASING				
Test Type	Date	Result	Unit	Status
Visual	04/11/2019			Fail
				Overall: Fail

<b>Location: SHOP FLOOR</b>				
Asset ID: 3452750	Description: EXTENSION LEAD	User: A. BARNES	Test Instrument: Seaward PrimeTest 350 04B-0195	
Comments: NO EARTH				
Test Type	Date	Result	Unit	Status
Earth Continuity	04/11/2019	> 20.0	ohm	Fail
				Overall: Fail

Total Tests: 2